



**NATIONAL  
SENIOR CERTIFICATE**

**GRADE 12**

**SEPTEMBER 2023**

**MECHANICAL TECHNOLOGY:  
WELDING AND METALWORK  
MARKING GUIDELINE**

**MARKS: 200**

---

This marking guideline consists of 12 pages.

---

**QUESTION 1: MULTIPLE-CHOICE QUESTIONS (GENERIC)**

- 1.1 C ✓ (1)
- 1.2 D ✓ (1)
- 1.3 C ✓ (1)
- 1.4 C ✓ (1)
- 1.5 A ✓ (1)
- 1.6 B ✓ (1)
- [6]**

**QUESTION 2: SAFETY (GENERIC)****2.1 Arc welding safety precautions:**

- Wear the correct PPE. ✓
- Ensure the electrode holder is well insulated. ✓
- The environment must be free of water and combustible materials. ✓
- Ensure the environment is well ventilated. ✓ (Any 3 x 1) (3)

**2.2 Pedestal drilling machine safety precautions:**

- Wear correct PPE. ✓
- Make sure all guards are in place. ✓
- Clamp the workpiece securely. ✓
- Use the correct drill bit. ✓
- Do not make any adjustment while the machine is in motion. ✓
- Use the correct speed. ✓
- Do not remove chips by hand. ✓ (Any 2 x 1) (2)

2.3 Manual guillotine maximum cutting thickness is 1,20 mm ✓ (1)

**2.4 2.4.1 Advantages of product layout:**

- Handling of material is limited to a minimum. ✓
- Time period of manufacturing cycle is less. ✓
- Production control is almost automatic. ✓
- Greater use of unskilled labour is possible. ✓
- Less total inspection is required. ✓
- Less total floor space is needed per unit of production. ✓ (Any 2 x 1) (2)

**2.4.2 Advantages of the process layout:**

- High machine utilisation because more than one product is manufactured. ✓
- Better supervision as a result of subdivision of processes. ✓
- Less interruption in flow of work when machines become defective. ✓
- Lower equipment cost, since one machine can produce more than one product. ✓
- Better control of total manufacturing cost. ✓
- Greater flexibility in the production process. ✓ (Any 2 x 1) (2)

**[10]**

**QUESTION 3: MATERIALS (GENERIC)****3.1 Purpose of case hardening:**

- To produce a hard case over ✓ and tough core. ✓ (2)

**3.2 Using high carbon steel for case hardening**

- The hardness will penetrate the core. ✓ (1)

**3.3 Factors of hardness:**

- Work piece size ✓
- Quenching rate ✓
- Carbon content ✓ (3)

**3.4 Types of quenching mediums:**

- Water and salt (brine) ✓
- Tap water ✓
- Liquid salts ✓
- Molten lead ✓
- Soluble oil and water ✓
- Oil ✓ (Any 3 x 1) (3)

**3.5 Colour coding of engineering materials:**

- To identify the type of materials as well as the carbon content of steel ✓ (1)

**3.6 Types of tests:**

- 3.6.1
- Filing test ✓
  - Machining test ✓ (Any 1 x 1) (1)

- 3.6.2
- Sound test ✓
  - Spark test ✓ (Any 1 x 1) (1)

- 3.6.3
- Bending test ✓ (1)

**3.7 Machine for spark test:**

- Pedestal grinding machine ✓ (1)

**[14]**

**VRAAG 4: MULTIPLE-CHOICE QUESTIONS (SPECIFIC)**

4.1 D ✓

4.2 D ✓

4.3 C ✓

4.4 A ✓

4.5 A ✓

4.6 D ✓

4.7 A ✓

4.8 B ✓

4.9 A ✓

4.10 A ✓

4.11 D ✓

4.12 B ✓

4.13 A ✓


4.14 D ✓

(14 x 1) **[14]**

**QUESTION 5: TERMINOLOGY (TEMPLATES) (SPECIFIC)**

5.1 Other side up ✓ (1)

5.2 Sketch of roof truss:



✓✓✓✓✓✓✓✓

(6)

5.3. Calculations of steel ring:

5.3.1 Mean  $\Theta$  = Outside  $\Theta$  – plate thickness

**OR**

Inside  $\Theta$  + plate thickness

Mean  $\Theta$  = 520 – 42 ✓

= 478 mm ✓

Mean Circumference =  $\pi$  x mean  $\Theta$


=  $\pi$  x 478

= 1501,87 mm ✓

Rounded of to 1 502 mm for one ring. ✓

(4)

5.3.2



(4)

- 5.4 A – Contour symbol ✓
- B – Finish symbol grinding ✓
- C – Length of weld ✓
- D – Pitch of weld ✓
- E – Weld all round ✓
- F – Arrow ✓
- G – Finish symbol machining ✓
- H – Tail ✓

(8)

**[23]**

**QUESTION 6: TOOLS AND EQUIPMENT (SPECIFIC)**

- 6.1 A – Current adjuster ✓  
 B – Electrode terminal ✓  
 C – Electrode holder ✓  
 D – Electrode ✓  
 E – Arc gap ✓  
 F – Earth terminal ✓  
 G – Earth clamp ✓  
 H – Current scale ✓ (8)
- 6.2 Metal inert gas ✓ (1)
- 6.3 CO<sub>2</sub> and Terrell ✓✓ (2)
- 6.4 The *power saw* is used to rough-cut large sections of metal ✓ before they are further machined or used in manufacturing. It uses a reciprocating movement. ✓  
 The *band saw* cut in a horizontal position continuously in a forward direction ✓ due to the fact that the band is continuously moving in a circular path. ✓ (4)
- 6.5 Stock ✓  
 Mixer ✓  
 Nozzle ✓ (3)
- [18]**

**QUESTION 7: FORCES (SPECIFIC)**

- 7.1 7.1.1 **Stress**  

$$\text{Stress} = \frac{\text{LOAD}}{\text{AREA}}$$

$$= \frac{80 \times 10^3}{\frac{\pi D^2}{4}} \checkmark$$

$$\pi D^2 = \frac{4 \times 80 \times 10^3}{30 \times 10^6} \checkmark$$

$$D^2 = \frac{4 \times 80 \times 10^3}{\pi \times 30 \times 10^6} \checkmark \checkmark$$

$$D = 58,2 \text{ mm} \checkmark$$
 (5)

- 7.1.2 **Strain**  

$$\text{Young's Modulus} = \frac{\text{STRESS}}{\text{STRAIN}}$$

$$\text{Strain} = \frac{\text{Stress}}{\text{Young's modulus}} \checkmark$$

$$= \frac{30 \times 10^6}{90 \times 10^9} \checkmark$$

$$\text{Strain} = 0,00033 \checkmark$$
 (3)

### 7.1.3 Change in length

$$\text{Strain} = \frac{\text{Change in length}}{\text{Original length}}$$

$$\text{Change} = \text{Strain} \times \text{Original length} \checkmark$$

$$= 0,00033 \times 4 \checkmark$$

$$= 0,00133 \text{ mm} \checkmark$$

(3)

### 7.2 7.2.1 Reactions

Take reactions RL and RR

$$\text{RR} \times 10 = (3 \times 3) + (10 \times 4) + (6 \times 7) \checkmark$$

$$= 9 + 40 + 42$$

$$= 91 \checkmark$$

$$\text{RR} = 9,1 \text{ N} \checkmark$$

$$\text{RL} \times 10 = (6 \times 3) + (10 \times 6) + (3 \times 7) \checkmark$$

$$= 18 + 60 + 21$$

$$= 99 \checkmark$$

$$\text{RL} = 9,9 \text{ N} \checkmark$$

(6)

### 7.2.2


$$\text{BM}_A: (9,9 \times 3) = 29,7 \text{ N/m} \checkmark$$

$$\text{BM}_B: (9,9 \times 5) - (3 \times 2) = 43,5 \text{ N/m} \checkmark\checkmark$$


$$\text{BM}_C: (9,9 \times 7) - (3 \times 4) - (10 \times 3) = 27,3 \text{ N/m} \checkmark\checkmark$$

(5)

7.3 Framework:



Member	Strut	Tie	Force
AE	✓✓		15,3 N ✓
BG	✓✓		11,3 N ✓
CH	✓✓		12,2 N ✓
FG	✓✓		6,9 N ✓
EF			
DE		✓✓	13,25 N ✓
DF		✓✓	13,25 N ✓
DH		✓✓	6,2 N ✓
GH		✓✓	7 N ✓



Guide

(23)  
[45]

**QUESTION 8: JOINING METHODS (INSPECTION OF WELDS)**

- 8.1
- The liquid dye penetrant is sprayed onto the clean surface being inspected. ✓
  - Allow a short time for the liquid to penetrate. ✓
  - Remove the excess dye with a cleaner (solvent). ✓
  - Wash the surface and allow to dry. ✓
  - When the surface is dry, spray it with a developer to bring out the colour, which was sprayed on and penetrated any cracks or pin holes. ✓
  - Fluorescent liquids are also used for the surface being inspected. ✓✓
  - After a short while, remove the liquid with a cleaner and wait for it to dry. ✓
  - A black-light source (ultraviolet light) is then brought up to the surface. ✓
  - Areas where the fluorescent liquid has penetrated will show up under the light. ✓
- (Any 8 x 1) (8)
- 8.2 It refers to a cavity-type formed by gas ✓ during the solidification ✓ of molten weld metal. ✓ (3)
- 8.3
- Shape of profile ✓
  - Uniformity of surface ✓
  - Overlap ✓
  - Undercutting
  - Penetration bead
  - Root groove
- (Any 3 x 1) (3)
- 8.4
- Slag inclusion ✓
  - Porosity ✓
  - Lack of fusion ✓
  - Oxidised or burnt metal ✓
- (4 x 1) (4)
- 8.5
- Correct flame for the work at hand ✓
  - Correct angle of welding torch and welding rod ✓
  - Depth penetration and amount of fusion
  - The rate of progress along the joint
- (Any 2 x 1) (2)
- 8.6
- Good for ferrous and non-ferrous metals ✓
  - Low cost ✓
  - Easy to apply ✓
  - Minimal training required
- (Any 3 x 1) (3)
- [23]**

**QUESTION 9: JOINING METHODS (STRESSES AND DISTORTION) (SPECIFIC)**

- 9.1
- Do not over weld. ✓
  - Control the fill up. ✓
  - Use intermittent welds. ✓
  - Use the smallest leg size for fillet welds. ✓
  - Use minimum root opening.
  - Use minimum included angle.
  - Select joints that use minimum weld metal. (Any 4 x 1) (4)
- 9.2
- Do not over weld. ✓
  - Proper preparation is needed. ✓
  - Use intermittent welding. ✓
  - Use as few passes as possible. ✓
  - Place welds near the neutral axis. ✓
  - Use back step welding.
  - Anticipate shrinkage forces.
  - Plan the welding sequence.
  - Minimise welding time. (Any 5 x 1) (5)
- 9.3
- Low carbon steel (0,15–0,30%) ✓ known as mild steel. ✓  
 Medium carbon steel (0,31–0,70%) ✓ known as spring steel. ✓  
 High carbon steel (0,71–1,5%) ✓ known as tool steel. ✓ (6)
- 9.4
- It is common in gas metal arc welding ✓ and comprises of droplets of molten material ✓ that are generated at or near the welding arc. ✓ (3)
- [18]**

**QUESTION 10: MAINTENANCE (SPECIFIC)**

- 10.1
- To accommodate multiple technicians to do maintenance, ✓ using their own locks. ✓ (2)
- 10.2
- If excessive loads are applied onto the spindle bearings, ✓ the grinding wheel and the grinding machine motor. ✓ (2)
- 10.3
- The journals and bearings/bushes must be well lubricated. ✓
  - Failure to lubricate the components will result in friction and wear of the components. ✓ (2)
- 10.4
- To monitor the machine's condition. ✓
  - To assist in upholding warranties and guarantees that forms part of the service agreements. ✓ (2)
- [8]**

**QUESTION 11: TERMINOLOGY (SPECIFIC)**

- 11.1 11.1.1 Length CG =  $\sqrt{60^2 + 130^2 + 260^2}$  ✓  
=  $\sqrt{88\ 100}$   
= 296,82 mm ✓ (2)
- 11.1.2 Length BG =  $\sqrt{60^2 + 175^2 + 260^2}$  ✓  
=  $\sqrt{101\ 825}$   
= 319,10 mm ✓ (2)
- 11.1.3 Length AE =  $\sqrt{60^2 + 160^2 + 260^2}$  ✓  
=  $\sqrt{96\ 800}$   
= 311,13 mm ✓ (2)
- 11.1.4 Length GD =  $\sqrt{130^2 + 140^2 + 260^2}$  ✓  
=  $\sqrt{104\ 100}$   
= 322,43 mm ✓ (2)
- 11.1.5 Length HC =  $\sqrt{40^2 + 130^2 + 260^2}$  ✓  
=  $\sqrt{86\ 100}$   
= 293,43 mm ✓ (2)
- 11.1.6 Length HK =  $\sqrt{130^2 + 260^2}$  ✓  
=  $\sqrt{84\ 500}$   
= 293,43 mm ✓ (2)
- 11.2 11.2.1 Length AB =  $\pi \times D \div 2$  ✓  
=  $\pi \times 800 \div 2$  ✓  
= 1 256,8 mm ✓ (3)

11.2.2 Circumference of small circle:

$$\text{Circumference} = \pi \times D \checkmark$$

$$= \pi \times 350 \checkmark$$

$$= 1\,099,7 \text{ mm} \checkmark \quad (3)$$

11.2.3 Length 0 – 2:

$$0 - 2 = D \div 2 \checkmark$$

$$= 350 \div 2 \checkmark$$

$$= 175 \text{ mm} \checkmark$$

(3)

**[21]**

**TOTAL: 200**